



MEIDINGER BLOWER WIRING DIAGRAMS

110 VAC
Single Phase




Move Capacitor lead from
one feed line to the other
to reverse motor rotation

220 VAC
Single Phase



108 VAC (low Voltage)
Three Phase



Switch any two feed lines
to reverse motor rotation

208-240 VAC (high Voltage)
Three Phase

